

<b>GEGENSTAND:</b> SUBJECT:	Modifikation des Fahrventils Modification of the main burner valve
<b>BETROFFEN:</b> AFFECTED:	fire balloons G und fire balloons S (EASA.BA.016 und EASA.BA.010), alle Hüllengrößen fire balloons G and fire balloons S (EASA.BA.016 and EASA.BA.010), all envelope sizes
<b>DRINGLICHKEIT:</b> URGENCY:	Nicht anwendbar (Ausführung ab sofort) Not applicable (effectuation instantly)
<b>GRUND:</b> REASON:	Produktverbesserung Improvement of product
<b>MASSNAHMEN:</b> MEASURES:	Das geltende Flughandbuch Ausgabe Nov. 2001 Änderung 19 vom Februar 2017 oder eine später anerkannte Ausgabe sind zu verwenden. Für die Wartung des Ventils ist zusätzlich Wartungshandbuch Anhang 3 zu verwenden. Der Brenner wurde mit einem neu konstruierten Fahrventil ausgestattet um die Wartung und Reparatur zu vereinfachen und die Leistung des Brenners zu steigern. Appliance of the current issue of the flight manual Ausgabe Nov. 2001 Änderung 19 from February 2017 or later approved issues are to be utilized. The Maintenance manual appendix 3 is to be used additionally for the maintenance of the valve. The burner was equipped with a newly designed main burner valve to improve maintenance and repair methods and to increase the power of the burner.
<b>MASSE:</b> MASS:	Keine Änderung des Brennergewichts No change of burner weight
<b>HINWEISE:</b> NOTES:	keine None

Theo Schroeder fire balloons GmbH

08.06.2017

Datum  
date



Unterschrift  
signature

Alexander Plein  
Technical engineer